## CERTIFIED LAND CORNER RESTORATION

	TATIFIED LAND CORN	ER RESIONALIC	JIN	
State of Wisconsin  County of Forest	- -			
County of Forest	<b>5.</b>			
I William B. Cochrane I found evidence of the East Q Township 37 North hereon; and that from this evidence petuate the original location of the	uarter Range 16 Ea nce I established a new mo	corner of st, Fourth	Section 10 h Principal Meridian	, as described
Description of original monument	and accessories and subse	quent restorations	•	
Surveyed in 1859 by James M North between sections 10 a Tamarack, 10, N18°E, 24 1ks Tamarack, 12, S42°W, 18 1ks	cBride nd 11. 40.0 chains s			
Description of corner evidence for	und:			
Fallen tamarack, 12" diamet At a point N42°E, 18 1ks. f bears N18°E, 24 1ks. No evidence of a post was f	rom the above bearing		ack stump	
Description of monument and accordent accordent and accordent accordent and accordent accordent and accordent ac	ed distances and beari eter, galvanized pipe, 37N, R16E, 1/4, S10, ear:	ngs of the ori 5 feet long,	ginal evidence for filled with conc	rete
•	43716183	H P	SURV	E de la
Sec. 10	1977  Colored William B.	Cochrane	naue Title Survey Tec	hnician
	(County Surveyor, Registration Notice of Register of	loS-1107	MOLIDITAL	113304
Corner monument restored	I hereby certify that the on the 13th day of No	within instrument February	was filed in this of 19.78, and wa	fice for record
Township 37 North Pane	Signature Ligens	(I / I)	•	