Stock No. 26273

PLAT OF SURVEY FOR CERTIFIED LAND CORNER RESTORATION AND ESTABLISHMENT

Sheet 1 of 5

BEING THE CORNERS FOR THE W 1/2 - NE 1/4, S 1/2 - SE 1/4, S 1/2 - SW 1/4, NW 1/4 - SW 1/4 AND NW 1/4 OF SECTION 13, T. 39 N. R. 13E., FOURTH PRINCIPAL MERIDIAN

COUNTY OF FOREST, STATE OF WISCONSIN

S.12_ **S.7** 3017.66 S,13 S.18 E I/16 1508.83 N 800 16, 13,E 1508.83 N 86º 59' 22"E S.II \ S.I2 3017.67 S.14 S.13 2472.71 000 57 W"15'60-10N 4861.06 PVT. U.S.A. 2398.31 U.S.A. 4796.61 144.00 . M.C. 1485.21 1485.22 C1/4 CE 1/16 CWI/16 5955.74 N 85º 40'50" E 1330.86 1492.65 2661,71 1/4 1492.66 1265.12 2464.20 PVT. 1232.1 PVT. 199.15 U.S.A. N 86° 56' 31"E CS1/16 2957.69 2965.II N 02º 13' 12" N 86°56'19"E 1482.55 NO0°56'49" 1482.56 1330.85 NOIº 22' 56" W NO1047' 23"W U.S.A. U.S.A. 1199.1 U.S.A. **S.18** S.13 2946.39 S.19 1473.19 5892.78 1473.20 **S.14** 3.13 N 88° 12' 48" E 1/4 S.24 SCALE | " = 1000 1000 1000

Railroad Spike

2½ inch diameter aluminum pipe monument 36 inches long with an aluminum cap 1 inch diameter aluminum pipe monument 36 inches long with an aluminum cap 1 inch diameter aluminum pipe monument 60 inches long with an aluminum cap

Scale in feet LEGEND

2 inch I.D. iron pipe monument with a brass cap

 $2\frac{1}{2}$ inch diameter aluminum pipe monument 60 inches long with an aluminum cap Boundary line marked to Forest Service standards

Bearings are true bearings as referenced to a solar observation taken at the intersection of State Highway 55 and Jones Creek located near the Southwest corner of Section 13.

FOREST CO SURVEYOR

FILE # 391313 - 19921002

DATE ______BY ____

• 0 • • • •

Note:

FORM NO. 985-A

Stock No. 26273

Sheet 2 of 5

SURVEY NOTES

This survey was made by Gary L. Pisoni, a Registered Land Surveyor in the State of Wisconsin, for the U.S.D.A., Forest Service, for the purpose of recovering, restoring, establishing, marking, and perpetuating the corners and boundary lines of U.S. Government Land on the perimeter and within Section 13, Township 39 North, Range 13 East, Fourth Principal Meridian, Forest County, State of Wisconsin, as shown on the plat map herewith.

The Original Government Sub-division of this township was done in 1865 by William E. Daugherty and Alex McDill. The East township line was done in 1858 by Artemas Curtis. Dependent resurvey was done in 1978 by Gary L. Kratz and Michael J. Avery.

The bearings between corner positions are true bearings referenced to a solar observation which was taken at the intersection of State Highway 55 and Jones Creek located near the Southwest corner of Section 13. All distances shown thereon are in feet and hundredths of feet. The control traverse was measured by use of electronic distance measuring equipment.

The accuracy of this survey exceeds the State requirements of 1 in 3000.

The field notes and a copy of the Plat of Survey are on file in the Forest Supervisor's Office at Rhinelander, Wisconsin.

CORNERS RECOVERED AND RESTORED

Northwest Section Corner

Corner restored from a Dependent Resurvey in 1978 by Gary L. Kratz and Michael J. Avery. Corner position determined at the intersection of the State Highway 55 and Hartline Road extending East.

1978 Corner References:

Ash	6"	N 41°E	54.12 feet
Ash	6"	S 72°E	58.08 feet
Ash	6"	s 54°W	34.32 feet
Ash	7"	N 57°W	40.92 feet
1990 Corner References:			
Ash	6"	N 41°E ·	54.11 feet
Ash	6"	s 70°E	58.11 feet
Ash	7"	s 55°W	34.74 feet
Ash	7"	N 39°W	41.50 feet

North Quarter Corner

Corner position restored by using the centerline of Forest Road No. 3854 and at midpoint between the Northwest and Northeast Section corners of Section 13.

Corner References:

Basswood	10"	N 50°E	44.84 feet
Sugar Maple	6"	S 52°E	64.01 feet
Basswood	11"	s 09°W	60.45 feet
Ash	9"(dbl)	N 62°W	72.37 feet
Steel sign po	st	North	18.75 feet

Stock No. 26273

Sheet 3 of 5

3. MOI CHEASC DECETOR COLLECT	3.	Northeast	Section	Corner
-------------------------------	----	-----------	---------	--------

In 1975 Jean Resvick RLS U.S.F.S. restored the corner position. 1985 Corner References by William Cochrane RLS:

Spruce	16"	N 29°E	51.62	feet
Aspen	12"	south	66.74	feet
Aspen	14"	N 32°W	54.18	feet
Steel sign	post	Northeast	3.50	feet

East Quarter Corner

Corner position restored in 1985 by William Cochrane RLS U.S.F.S. from a recovered 4"x4" wood post and bearing tree set by Melindy in 1928 for the witness corner to the quarter corner location. Quarter corner located in middle of a stream. 1985 Corner References:

Witness Corner	N 01	°47'27"₩	144.00 feet
References to the Witness	Corner:		
Spruce	9"	N 08°E	32.13 feet
Tamarack	10"	N 60°W	82.35 feet
Steel sign post		Northeast	3.00 feet

South Sixteenth Corner Between Sections 13 and 18 Corner position at midpoint and on line between the East quarter corner and the Southeast Section corner. 1988 Corner References:

Cedar	10"	S 70°E	31.22	feet
White Birch	8"	N 44°W	18.44	feet
Steel sign p	post	Northeast	1.00	feet

Southeast Section Corner

Corner position restored in 1985 by William Cochrane RLS U.S.F.S. by using Melindy's recorded distance from the East quarter corner witness post on a straight line through the South Sixteenth corner post between Sections 13 and 18 set by Melindy in 1929. 1985 Corner References:

Tamarack	10"	s 78°E	61.18 feet
Tamarack	16"	S 33°E	68.70 feet
Steel sign	post	North	0.50 feet

7. <u>South Quarter Corner</u> Corner position restored at proportionate distance and on line between the Southwest and Southeast Section corners of Section 13.

Corner References:

White	Spruce	13"	S	44°W	53.22	feet
White	Spruce	11"	N	74°W	39.72	feet
White	Spruce	10"	N	27°W	16.75	feet
White	Spruce	12"	N	79°E	47.47	feet
Steel	sign post	:	S	35°E	0.66	feet

Southwest Section Corner

Corner position restored by single proportionate distance and on line between the Northwest Section corner of Section 13 and the West quarter corner of Section 24. Corner Reference:

Cedar	13"	N 49°E	43.29 fee
Red Maple	8"	S 56°E	15.30 fee
Red Maple	8"	s 14°W	37.31 fee
Red Maple	7"	N 58°W	29.22 fee
Steel sign ;	post	North	1.15 fee

Stock No. 26273

Sheet 4 of 5

West Ouarter Corner

Corner position restored by single proportionate distance and on line between the Northwest Section corner of Section 13 and the West quarter corner of Section 24.

Corner References:

Sugar Maple	7"	N	49°E	64.34	feet
Sugar Maple	6"	S	64°E	62.96	feet
Sugar Maple	8"	S	50°W	37.96	feet
Sugar Maple	7"	N	44°W	40.79	feet
Witness Corner	2"x36"	mon.	N 85°40'50"E	42.11	feet
Steel sign post	5	We	est	23.98	feet

CORNERS ESTABLISHED

East Sixteenth Corner Between Sections 12 and 13 Corner position established at midpoint and on line between the Northeast Section corner and the North quarter corner. Corner References:

Sugar Mapl	le 7"	N 65°E	33.68 feet
Sugar Map	le 12"	N 87°W	34.58 feet
Steel sign	n post	South	0.64 feet

Center East Sixteenth Corner

Corner position established at midpoint and on line between the East quarter corner and the Center quarter corner. Corner References:

Balsam Poplar	7"	S 14°W	34.93 feet
Balsam	7"	N 66°W	32.01 feet
Steel sign post	3	N 14°W	0.52 feet

Center Ouarter Corner

Corner position established at the intersection of the straight lines between opposing quarter corner positions on the perimeter of the section.

Corner References:

Cedar	13"	N 8	32°E	69.25	feet
Cedar	14"	s 4	10°E	28.27	feet
Steel sign	post	N ()9°W	0.91	feet

Center West Sixteenth Corner

Corner position established at midpoint and on line between the West quarter corner and the Center quarter corner. Corner References:

Sugar Maple	6"	N 41°E	5.88 feet
Sugar Maple	6"	N 47°W	21.49 feet
Steel sign pos	t	North	0.48 feet

5. <u>Southwest Sixteenth Corner</u> Corner position established at the intersection of the straight lines between opposing sixteenth corner positions on the perimeter of the Southwest quarter of Section 13. Corner References:

LCI CHOCD.			
White Spruce	12"	N 59°W	31.23 feet
Balsam	6"	N 13°W	25.01 feet
Steel sign pos	st	s 45°W	0.56 feet

6. <u>Center South Sixteenth Corner</u> Corner position established at midpoint and on line between the South quarter corner and the Center quarter corner. Corner References:

Steel sign po	ost No	orth	0.62	feet
Steel sign po	ost So	outh (0.90	feet
Steel sign po	ost We	est (0.46	feet

FORM NO. 985-A

Stock No. 26273

Sheet 5 of 5

SURVEYOR'S CERTIFICATE

State of Wisconsin)ss County of Forest)

I, Gary L. Pisoni, a Cadastral Surveyor, and a Registered Land Surveyor in the State of Wisconsin, hereby certify that I have surveyed and sub-divided Section 13, Township 39 North, Range 13 East, Fourth Principal Meridian, State of Wisconsin.

The plat map and survey notes herewith are a correct representation of the land surveyed and divided. I have surveyed and sub-divided said section in accordance with the rules for the survey of public lands and with the statutes of the State of Wisconsin.

Date of Survey:

1990

GARY LEE
PISONI
S-1634
IRON RIVER,
MI

Cadastral Surveyor

R.L.S. State of Wisconsin

Certificate S-1634

Survey requested by;

District Ranger

Date

