<b>VEDTICIED</b>	IAND	CODNED	RESTORATION
CERTIFIED	LAND	CORNER	KESTOKATION

	1	<b>D</b> 1	7
Index	No.		

History of original corner establishment:

Surveyed in 1859 by James McBride

40.00 chains N1°E between Sections 22 and 23 set post for quarter corner

Tamarack 8", N33°E, 35 lks.

Tamarack 7", S6°W, 17 lks.

Description of corner evidence found:

Cedar post, scribed in place Tamarack stump, N33°E, 21.4 ft. (32.42 lks) Tamarack stump, S6°W, 11.0 ft. (16.67 lks)

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced cedar post with 2-inch inside diameter, galvanized iron pipe, 5 feet long, flanged at bottom, filled with concrete, with brass cap marked:

T34N R14E 1/4 S22 S23 1964 S-802 from which the following blazed and scribed new bearing trees bear:

Tamarack 4", N59 E, 19.10 ft. (28.94 lks)

Spruce 5", N50 W, 21.00 ft. (31.82 lks)

Power pole, Number 94, S52 W, 35.20 ft. (53.33 lks)

		<b>2</b>		· 2	
Dated at Rhinelander	, Wis., this	J-rel	day of	elegus	, 19 <i>6 7</i>
Signature dan F. Reeva	Title	Cadastral	Surveyor	Regi	stration No. S-802
Signature J. County Surveyor, Regis	tered Land Surveyor	, or other duly a	uthorized offici	ial)	
Office of Register of Deeds, County of instrument was filed in this office for reat	Forest			. I hereby	certify that the within
instrument was filed in this office for r	ecord on the	21	day of	Oct	19 64
at 11 o'clock A. M. Doo	:.#89304 Vol.	1 Page P-	-17 CORNEI	RESTORATI	ONS
			SQ.	ROA	
anna Geter	2027			a Dan Dan Dan Dan Dan Dan Dan Dan Dan Da	
(Register of De	eds)				