## CERTIFIED LAND CORNER RESTORATION

	INTITLD LAND C	OMITER ME				
State of Wisconsin						
County of Forest	<b>5.</b>			•		•
I Jean F. Resyick I found evidence of the Sour Township 34 North hereon; and that from this evidence petuate the original location of the	th East Section. Range 16 East ce I established a n	t	corner of , Fourt	Section. th Principa	6 l Meridian, as	described
Description of original monument	and accessories and	subsequent	restorations	S: .		
Survey in 1858 by James Mcl. Cedar, 10 inches, bears N42 B. Ash, 12 inches, bears S2 Cedar 12 inches, bears S75 Cedar 10 inches, bears N17	OE 21 lks. 26°E 32 lks. W 30 lks.	is North be	tween se	ctions 5	and 8, set	post
	•		•	•	•	
Description of corner evidence for	and:			•	•	
1. Remains of wood post 2. Remains of Cedar stump, 3. Black Ash stump, bears 4. Cedar snag bears S75°W 5. Remains of Cedar stump	S26 <sup>o</sup> E 32 lks. 3 lks.					
		•				
	•	_		· ·		
Replaced wood post with 2 is with concrete with a brass From which the following not Cedar 8 inches bears \$60°E Cedar 5 inches bears \$40°W Steel post N.E. 1.0 ft.	nch inside diame cap marked: T34N w bearing trees 15.74 ft.	ter galvan I, R16E S6,	ized pipe	e, 3 ft.	long filled S-802	•
					JE RE RH	AN F. SVICK NELATIVETI. WIS.
	Resident witnesses	•••••••••••	······································		**************************************	88988888
Sec. 6	Signature Jean (County Surveyo	F. Resvick or, Registered L	and Surveyo	Title	2/ day of  Land Survey uly authorized of  ENT No. 1()	yor fficial)
	Surveyors Registrat	•		_		3U3U
Corner monument restored	Office of Regist I hereby certify the on the 5th No	at the within day of API Page No	instrument	was filed 19.74 of County	in this office L., and was file Records.	ed in Book
Township 34 North Range	Signature.	general 6	laligns	Title Re	gister of D	eeds