State of Wisconsin

O = Corner monument restored.

| CERTIFIED LAND CORNER RESTORATION | | | | | |
|-----------------------------------|-----------|------|--------|-------------|---|
| | CERTIFIED | IAND | CORNER | RESTORATION | ١ |

History of original corner establishment:

Hemlock Sugar

Description of corner evidence found:

2" iron pipe 5' long with brass cap set by C.E. Walker in 1940

Description of monument and accessories I established to perpetuate the original location of this corner.

Left monument set by Walker

Ties:

Hemlock Hemlock s64W s7կe.

24.68 feet 8.80 feet

THOMAS I ARNOTI S-887

Dated at Crandon , Wis., this 30th day of 0ctober , 1975

Office of Register of Deeds, County of Forest , I hereby certify that the within instrument was filed in this office for record on the 30th day of October 19.75.

Document Number 108108