Original subdivision by James Nowlin Sept. 11 -- Sept 21, 1865

2" iron pipe 5! long with brass cap set by C.E. Walker in 1940

CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

Description of corner evidence found:

Hemlock

Birch

Ties:

Maple

Maple

30 Lks. 28 Lks.

	HOMAS	Page	THE STATE OF THE S
	ARNO		
*	5-887	1	**************************************
	wis.		الله
White State of the	YY 13.	WENTER OF	
Applified Application of the Control	SUF	Milita	_
rv ·	***************************************	19 ₋	76
		,	

Dated at Crandon	, Wis., this	8th	day of	January		, 197
Signature I homean Acard	Title	Surveyor	;	Regis		
(County Surveyor, Register	red Land Survey	or, or other duly	authorized off	icial)		
Office of Register of Deeds, County of	For	est 8th	day of	Janua	certify that ry	t the wi
at o'clock M.	JOI OIL CHO			et la legal	•	
Register of Deed	ml		Docume	n t Number	1085	23
(Register of Deed	is)	.•.			•:	

State	of	Wisconsin
_	_	. 1

I Thomas R. Arnott , do hereby certify that on the 23rd day of December , 19.75, I found evidence of the 1/4 corner of sections 2 & 11

Township 35 , North, Range 13 E , Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:			
	B	•	

 -		
	SEC - :	
	<u>2</u> 1 1 1 1 1 1 1 1 1	-
	$\frac{1}{i} \frac{1}{i} \frac{1}{i} - $	_

O = Corner monument restored.