CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

Original subdivision by James Nowlin Sept. 11, - Sept. 21, 1865

Hemlock Birch

Description of corner evidence found:

2" iron pipe 5' long with brass cap set by C.E. Walker in 1940

Description of monument and accessories I established to perpetuate the original location of this corner.

Left monument set by Walker

Ties:

NJ 6M. 0ak N57E Maple S22E Balsam

26.83 feet 15.10 feet 23.72 feet

THOMAS R ARNOTT S-887

Dated at Crandon Wis., this 18th day of February 19.76... (County Surveyor, Registered Land Surveyor, or other duly authorized official) instrument was filed in this office for record on the......18th.....day of......February........... 19...76. at 11 o'clock M. Document Number

108769