State of Wisconsin

SS.

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

N28E 26 Lks. Ironwood 10 14 S62W. 9 Lks. Sugar

Description of corner evidence found:

2" iron pipe 5' long with brass cap set by C.E. Walker in 1940

Description of monument and accessories I established to perpetuate the original location of this corner.

Wie this

Left monument set by Walker


Crandon

Ties:

N28E Maple 0ak 12

19.75 feet 15.72 feet

23rd day of



Dated at Crandon , Wis., this.	23rdday of	January.	19.76
Signature Across Mines Title (County Surveyor, Registered Land Surveyor)	Surveyor yor, or other duly authorized office	Regi	stration No.S-887
Office of Register of Deeds, County ofinstrument was filed in this office for record on the	Forest 23rd day of	, I hereby January	certify that the within
at 3. o'clock P. M.		_	108626

.Deputy

(Register of Doess