CERTIFIED LAND CORNER RESTORATION

State of Wisconsin County of Forest I Milo E. Stefan , do hereby certify that on the 21st day of October , 19 82, I found evidence of the West 4 corner of Section 9 Township 35N , Range 15E , Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner: Description of original monument and accessories and subsequent restorations: Surveyed in 1859 by James McBride 40.00 chains, set 4 section wood post
I Milo E. Stefan , do hereby certify that on the 21st day of October , 19 82. I found evidence of the West 1 corner of Section 9 Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner: Description of original monument and accessories and subsequent restorations: Surveyed in 1859 by James McBride
I found evidence of the West 4 corner of Section 9 Township 35N Range 15E Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner: Description of original monument and accessories and subsequent restorations: Surveyed in 1859 by James McBride
Surveyed in 1859 by James McBride
Hemlock, 12", S70E, 20 lks., 13.2 feet Hemlock, 16", N60W, 30 lks., 19.8 feet
Description of corner evidence found:
Found 5" x 5" x 2' Gedar post in mound of stone. Hemlock stump, 18" = 20", N6OW, 19.8 feet Hemlock stump remains, S7OE, 13.2 feet
Description of monument and accessories I established to perpetuate the location of this corner: Placed a 2" x 30" aluminum pipe in mound of stone with cap stamped as follows: T35N, R15E, S8, ½, S9, 1980, RLS-1558 From which the following bear: Sugar Maple, 8", S30E, 10.70 feet White Spruce, 5", S32W, 20.51 feet White Spruce, 13", N43W, 32.39 feet Steel sign post, NE, 1.4 feet DOCUMENT NO.
124183 WIS.
SURVE SON
Resident witnesses Dated at Rhinelander Wisconsin, this day of May 1982 Section 9 Signature Milo E. Stefan Title Land Surveyor
(County Surveyor, Registered Land Surveyor, or other duly authorized official)
Surveyors Registration No. RLS=1558 Office of Register of Deeds County of Forest
I hereby certify that the within instrument was filed in this office for record on the 12th day of September 1983, and was filed in Book No. Page No. of County Records.
Signature Signature Title Register of Deeds

ss.

State of Wisconsin

CERTIFIED LAND CORNER RESTORATION

County of Forest	•	
Township 35 North	day of October Quarter Corner of Section 9 October Corner of Section 9 Range 15 East Fourth Principal Meridiance I established a new monument and accessories as described is corner:	an, as described
Description of original monument	and accessories and subsequent restorations:	
Surveyed by James McBride in Set Wood Post. Hemlock 12", S70°E, 20 lks. Hemlock 16", N60°W, 30 lks.		
Description of corner evidence for	und:	
Wood post in mound of rock Hemlock Stump remains S70°E Hemlock Stump remains N60°W		
	essories I established to perpetuate the location of this corner: such by 30 inch aluminum pipe with cap stamped: o, R.L.S. 1558	
From which the following be Sugar Maple 8", S30°E, 10.76 W. Spruce 5", S32°W, 20.51'W. Spruce 13", N43°W, 32.39	'O'	MILO E-
	DOCUMENT NO. 119861	STEFAN S-1558 HINELANDER, WIS.
	Resident witnesses	Maria de la companya della companya
Sec. 9	Dated at Laona Wisconsin, this 3 day 19.80 Signature Milo E. Stefan Title Land Su (County Surveyor, Registered Land Surveyor, or other duly author Surveyors Registration No. 1558	rveyor
Corner monument restored	Office of Register of Deeds County of Fore I hereby certify that the within instrument was filed in this on the 2nd day of June 1981, and w No. Page No. of County Records Signature Land Many of Title Register	office for record vas filed in Book
Township35N, Range	Signature Liquis Section 9 Index No. G-9 Page	ge No.