O = Corner monument restored.

OFDICIED	LANID	CODNIED	DECTODATION
CERTIFIED	LAND	CORNER	RESTORATION

Index No.

History of original corner establishment:

Original survey done by James L. Nowlin June 2 - June 12, 1865

Birch 12 N10E 16 Lks. Birch 14 N80W 22 Lks.

Description of corner evidence found:

2" iron pipe 5' long with brass cap set by C.E.Walker in 1938 Old wood post found

Description of monument and accessories I established to perpetuate the original location of this corner.

Left monument set by Walker

Cedar	10	N53E	27.60 feet
Cedar	6	N53E S25W	19.05 feet
Cedar	8	N82W	13.82 feet

THOMAS R.
ARNOTT
S-887

WIS.
SURVENIENTERS

Dated at Crandon	, Wis., this	26	day of	Nov.	, 19. 76		
Signature Thomas Acust	Title	Title Surveyor			Registration NoS-887		
(County Surveyor, Regist	cred Land Survey	or, or other duly	y authorized officia	al)			
Office of Register of Deeds, County of Forest instrument was filed in this office for record on the				I hereby c	ertify that the within		
instrument was filed in this office for re	ecord on the	2	6 day of	Nov.	, 19.76		
at 3:30.o'clock P. M.							
EUGENE STATE			Document	Number:	1100		

Beleen Ochmidt Deputy

(Register of Deeds)