

CERTIFIED LAND CORNER RESTORATION

Index No. 2223

State of Wisconsin }  
County of Forest } ss.

History of original corner establishment:

Y. Birch 10 N52W 12 Lks.  
Hemlock 9 S37E 40 Lks.

I Thomas R. Arnott, do hereby certify that on the 5th day of December, 19 75, I found evidence of the 1/4 corner of sections 1 & 36 Township 35-36, North, Range 13 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

2" iron pipe 5' long with brass cap set by C.E. Walker in 1938

Resident witnesses:

.....  
.....  
.....


Description of monument and accessories I established to perpetuate the original location of this corner.

Left monument set by Walker

Trees:  
Maple 8 N34W 16.75 Feet  
Maple 6 N75E 18.37 feet



FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Crandon, Wis., this 15th day of December, 19 75.

Signature Thomas Arnott Title Land Surveyor Registration No. S-887  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Forest, I hereby certify that the within instrument was filed in this office for record on the 15th day of December, 19 75 at 11 o'clock A. M.

Eugene Stetson Document Number 108382  
(Register of Deeds)

By ..... Deputy

4301330020