	PUBLIC	1 8 5 1 5		MONUMENT	
11 5	DUBLIE	I AKUI		RACIDAL IRAN NI I	
\mathbf{u}	TINDI IL.	LANINI	THE STATE OF THE S	IATE VIALENTALE LA L	INI VARIO

Index	Nο	P -	9

State o	of Wisconsin	n } ss.	
County of	Forest	∫ ss.	
certify that or ofAug evidence of th corner ofS	n the 4th ust e West Qua section 21	, do hereb da _, 19 <u>94</u> , I foundarter	y d
16 East as described he I established	E, Fourth I ereon; and that a new monume hereon to perpe	, North, Rang Principal Meridian from this evidence ent and accessorie etuate the origina	e s
Resident with	esses:		
8848-714-4-6-7-1 8-88-88-88		************************	••
		7	_
			•
1	1	1 %	
			I

 SECTI	DN 21	· !
 ! !		! ! !
·	je je	

= Corner monument restored.

History of original corner establishment:

Original Government Survey in 1858 by James McBride. North between Sections 20 and 21, at 40.00 chains, set Quarter Section post, from which the following bear; Elm, 8", N 72° E, 30 lks; Sugar, 18", S 71° W, 6 lks.

Description of corner evidence found:

No corner evidence was recovered.

I re-established the corner position at proportionate distance and on line between the Southwest and Northwest Section corners of Section 21.

Description of monument and accessories I established to perpetuate the original location of this corner.

At the corner position, set a $2\frac{1}{2}$ " x 36" aluminum pipe monument with an aluminum cap stamped; T36N, R16E, 1/4, S.20, S.21, 1994, S-1634; from which the following new blazed and scribed bearing trees bear: (all measurements taken to a nail in side of tree)

Elm	7"	ท 35 ัพ	45.19	feet
Elm	8"	N 18 ⁰ E	35.15	feet
Black Cherry	8"	s 71°E	27.22	feet
Elm	8"	s 11°E	17.93	feet
Steel sign post		s 65°w	0.97	feet

Dated at Iron River, MI					
$\mathcal{A} = \mathcal{A}$			•		•
Signature Van L. From	Title	Land Surve	eyor	Regi	stration NoS-1634
(County Surveyor, Registered	Land Survey	or, or other duly	authorized offi	cial)	
Signature (County Surveyor, Registered Office of Register of Deeds, County of instrument was filed in this office for record	Foces	t .		I hereby	ceraify that the within
instrument was filed in this office for record	d on the	200	day of	Maic	19.97
at 1:30 o'clock 1 M.			•		

(Register of Deeds)

By Jul Soulieures

Jeputy

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None

- (r) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?
- (g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

Re-established through lost corner proportionate methods.

