CERTIFIED LAND CORNER RESTORATION
State of Wisconsin County of Forest ss.
I Jean F. Resvick do hereby certify that on the 9th day of May 19.73, IXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
Description of original monument and accessories and subsequent restorations: Surveyed in 1865 by H. & J.L. Nowlin 41.90 chains south corrected between sections 4 & 5, set post Cedar 10, S89E, 14 lks. Cedar 6, N68W, 15 lks.
Description of corner evidence found:
2 x 4 Cedar post, not scribed about 30 years old. Forest Service location poster on Cedar facing south dated 1957 and 1958 post is of Forest Service origin and appears to be set at a proportional distance but not on line between section corners. The distance between section corners measured 5176.04 feet on a magnetic bearing of NO1°58 E. Description of monument and accessories I established to perpetuate the xaisinax location of this corner: At the proportional distance of 2527.98 feet north on line between Section corner, set a 2 inch inside diameter, galvanized iron pipe, 3 feet long, filled with concrete to weigh 5 pounds per foot with brass cap stamped: T38N R14E 1/4 S5 S4 Maple 7, S31E, 17.48 feet Maple 9, N78W, 39.05 feet Set sign post 1.5 feet, northwest of monument North 1/2 mile measures 2648.06 feet North 1/2 mile measures 2648.06 feet
Resident witnesses Dated at Rhinelander Wisconsin, this 30/A day of Aug. 19.73 Signature Jean F. Resvick Title for June 19.73 (County Surveyor, Registered Land Surveyor, or other duly authorized deficial) Surveyors Registration No. 5-802 Office of REGISTER OF DEEDS County of FOREST I hereby certify that the within instrument was filed in this office for record on the 13th day of November 19.73., and was filed in Book No. 19.73 Corner monument restored Corner Restorations Resident witnesses. Dated at Rhinelander Wisconsin, this 30/A day of Aug. Title for file for
Signature Constitution Title Register of Deeds Township 38 north , Range 14 east Section 5 , Index No. C-9 , Page No.