W. C. MILLER CO., MILWAUKEE 448643

R9-5680-5 (7/15/64)

CE	RTIFIED LAND CORNER RESTORATION
State of Wisconsin County of Forest	S.
Township39 North	west quarter corner of Section 18 Range 12 East Fourth Principal Meridian, as described nee I established a new monument and accessories as described hereon to perise corner:
Surveyed in 1859 by William	from which: A pine snag, 12 in. dia., bears \$28E, 21 lks. A stump hole, bears \$150 %, 39 lks. A jack pine, 5 in. dia., bears \$160 30 E,
Description of corner evidence found: 1939 A Norway, 12 in. dia., bears S800W, 66 lks. Monument as described and in place. A jack pine snag, 5 in. dia., bears S160E, 33.00 ft. A red pine snag, 12 in. dia., bears S800W, 43.56 ft. A pine snag, 12" dia., bears S280E, 13.86 ft.	
Blazed and scribed the for A red pine, 14 in. dia., A red pine, 10 in. dia.,	essories I established to perpetuate the original location of this corner: llowing new bearing trees: N36° 30'W, 102.50 ft. or 155.30 lks. S40°W, 55.84 ft. or 84.60 lks. above ground by monument. JEAN F. RESVICK RHINELANDER, WIS.
Section 18 — Corner monument restored — =	Resident witnesses Dated at Rhinelander Wisconsin, this 2/st day of Feb. 19. 68. Signature Jean F. Resvick Title Cadastral Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official) Surveyors Registration No. S-802 DCC. 94229 Office of Register of Deeds County of Forest I hereby certify that the within instrument was filed in this office for record on the 27th day of February 19. 68., and was filed in Book No. I. Page No. of County Records. Signature Register of Deeds Signature Register of Deeds
Township 39 North, Range 12 East, Section 18, Index No. L-1, Page No.	