| HC.Miller Company [77] | Stock No. 262 | 食運動用各級和打打 人 | |
|------------------------|---------------|-------------|--|
| | | • | |

DOCUMENT

| U.S | PUBLIC | LAND | SURVEY | MONUMENT | RECORD |
|------|--------|------|--------|-----------|--------|
| U.U. | | | | MONORILIA | INCOME |

| | | 17 | 7 | |
|-------|-----|----|---|--|
| Index | No. | V | | |

| U.S |
|---|
| State of Wisconsin } ss. |
| County of <u>Forest</u> |
| I John H. Fisher, do hereby certify that on the day of February, 19 85, I found evidence of the North Quarter corner of Section 32 Township 39, North, Range 12 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories |
| as described hereon to perpetuate the original |
| location of this corner. |
| Resident witnesses: |
| None |
| · |
| |
| |
| |
| |
| |

| O = Corner m | onument restored. |
|--------------|-------------------|
|--------------|-------------------|

History of original corner establishment: Original Survey by William E. Daugherty, in 1859. Dependent resurvey in 1941 by H. D. Craig; at 41.52 proportionate distance set iron post 3 feet long, 2 inches diameter, 27 inches in the ground with brass cap stamped:

From which the following bear:

Norway Pine 9" N87°W 82 lks

Description of corner evidence found:

B.L.M. Monument as described above.

Description of monument and accessories I established to perpetuate the original location of this corner. Blazed and scribed the following new bearing trees:

| Red | Pine | 15" | N76°W | 44.3 feet |
|-----|-----------------|-----|-------|-----------|
| Red | Pine | 14" | S74°W | 21.3 feet |
| Red | Pine | 12" | N17°E | 48.3 feet |
| Red | Pine | 13" | S14°E | 15.5 feet |
| Set | steel sign post | | Nlo°E | 1.1 feet |

| Dated at | Winocqua | , Wis., this. | day of Male | , 198.5 |
|-----------|----------------------------|------------------|---|-------------------------------------|
| Signature | County Surveyor, Registere | Title Registered | Land Surveyor uly authorized official) | Registration No. S-836 |
| | | | | hereby certify that the within 1985 |
| at 1:10 | Paul Aschenles | | | |
| | (Register of Deeds) | | | |
| Ву | | Depu | ty | |

39-12


Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Found perpetuated location

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as gvidence or used for proportioning in determining the corner location?



(i) I. John H. Fisher

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

John H. Fisher 3/2/8

Affix Landic Striveyor Scal

CONS

JOHN H.

FISHER

S-836

MINOCQUA,

WIS.