CE	ERTIFIED LAND CORNER RESTORATION
State of Wisconsin	
State of Wisconsin County of Forest	\$.
Township 40 North	do hereby certify that on the 30th day of September 19 74, quarter corner of Section 19. Range 12 East Fourth Principal Meridian, as described nce I established a new monument and accessories as described hereon to peris corner:
Description of original monument	and accessories and subsequent restorations:
Survey in 1857 by Alfred M Dependent Resurvey in 1926 Set iron post 3 feet long, Hemlock 16, S16°45'E, 15 1 Hemlock 18, N40°00'W, 31 1	by Guy R. Veal 2 inches diameter with brass cap marked: ½, S24, S19, 1926 ks
* *	
Description of corner evidence for Monument as described above Hemlock 22, S17°E, 10.5 fe Hemlock stump 20, N40W, 20	et et
•	•
Description of manuscritizant acc Blazed and scribed new bea Hemlock 22, N5W, 13.73 fee Set steel sign post 0.5 fe	et '
	JEAN F. RESVICK RHING A JURIS. Resident witnesses
	Dated at Rhinelander Wisconsin, this 20 day of 200
Sec 19	Signature Jean F. Resvick Title Land Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official)
	Surveyors Registration No. S-802 Document Number 108877
Corner monument restored	Office of Register of Deeds I hereby certify that the within instrument was filed in this office for record on the 31st. day of March 19.75, and was filed in Book No. Restorations Page No. P-1 of County Records. Signature Register of Deeds
Township40 North, Rang	Signature Land Title Register of Deeds e 12 East Section 19 Index No. P-1 Page No.
44011	24 z pap