U.S. PUBLIC LAND SURVEY MONUMENT RECORD	<u> </u>
---	----------

1 m of any	Nia	S-	\mathbf{Q}	
Index	130	<u></u>		<i></i> .
	• •			

State of Wisconsin } ss.	History of original corner establishment:			
County of Forest I Gary L. Pisoni do hereby	Corner was set in 1980 by the U.S.F.S. under the direction of William B. Cochrane, a Registered Land Surveyor during the sub-division of Section 29.			
certify that on the 16th day of August 19.89, I found evidence of the North 1/16 corner of Sections 28 and 29 Township 40, North, Range 12E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original	U.S.F.S. set a 2½ inch diameter aluminum pipe monument 30" long with an aluminum cap, stamped to identify the corner. Corner references established: Sugar Maple 18" N. 28°W. 25.54 feet Steel sign post N. 50°W. 0.5 feet Maple 11" S. 58°W. 31.71 feet Description of corner evidence found: Monument as described and in place.			
location of this corner. Resident witnesses:	Corner references recovered: Sugar Maple 18" N 28 ⁰ W 25.54 feet Steel sign post N 50 ⁰ W 0.5 feet			
**************************************	\ 			
	Description of monument and accessories I established to perpetuate the original location of this corner. Blazed and scribed the following new bearing tree: Ironwood 5" S 55 E 12.37 feet			
	Lucas Disagram M1			
SECTION 29 ;	Dated at Iron River, MI , Wis., this 26th day of August , 19.89 Signature Jay J. Possur Title Land Surveyor Registration No.S-1634 (County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of Forest , I hereby certify that the with instrument was filed in this office for record on the 8th day of March , 19.90 at 1:00 o'clock P. M. (Register of Deeds)			
= Corner monument restored.	ByDeputy			

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence Location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

> 18" Sugar Maple N 28⁰W, 25.54 feet Steel sign post N 50°W, 0.5 feet North 1/16 Corner S29 S28

Gary L. 'Pisoni

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature L. Drawn

8-26-89 Date

Survey requested by:

(i)

District Ranger

PISONI

S-1634

IRON RIVER,

MI