CERTIFIED LAND CORNER RESTORATION

UE	EKITFIED LAND CORNER RESTOR	ATION
State of Wisconsin	_	
State of Wisconsin County of Forest	5.	
I found evidence of the West Township 41 North	st quarter corner, Range 14 East nonument and	Fourth Principal Meridian, as described
Description of original monument	and accessories and subsequent restora	tions:
Surveyed in 1865 by	William Daugherty een section 20 and 21, set ks. ks.	
with Forest Service stump S84W, 6 feet for nearly 40 years.	und: n mound of rock bears S45E, location poster. Poster is rom center of stump. This I therefore accept the po	dated 1936. Birch corner has been in place
Replaced squared stal	essories I established to perpetuate the c ke with a 2 inch inside dia feet long, filled with cor p marked	meter, galvanized,
T41N R14E	from which the following	r blazed and earthod now
141N R141 141N R141	bearing trees bear. Sugar 5, N4 Yellow Birch 16, N8	18E, 16.65 ft. 37E, 29.41 ft. 39W, 15.65 ft. 50ot SW of monument
	44114 20 2000	JEAN F.
	Resident witnesses	JEAN F. RESVICK
Sec. 21	Dated at Rhinelander W 19.70 Signature Jean F. Resvick (County Surveyor, Registered Land Sur	
	Surveyors Registration No. 5-802	$\Delta \Delta $
Corner monument restored	I hereby certify that the within instrumon the 23rd day of October No CORNER Page No Page RESTORATIONS Signature Later	MITitle Register of Deeds
Township 41 North , Range	e 14 East //, Section 21 //, In	ndex No. P-9, Page No