



PLAT OF SURVEY

FOR

DOROTHY KONWAL

The SW 1/4 - NW 1/4 & part of Government Lot 7, All in Section 3,
T35N R13E, Township of Lincoln, Forest County, Wisconsin

Cor. Established by
William B. Cochrane
S-1107 in 1981

NW Cor.
Gov't Lot 6
(NW 1/16 Sec.3)

FOREST CO SURVEYOR
FILE # 351303-20011127
DATE BY

Konwal

SW 1/4 - NW 1/4
39.78 Ac.

NW Cor.
Gov't Lot 7
(W 1/4 Sec.3)

SW 1/4 - NW 1/4
Gov't Lot 7

S 89°43'50" E
1320.47'
North Line of Gov't Lot 7

Cor. Established by
William B. Cochrane
S-1107 in 1981

Cottage
Garage

S 89°43'50" E
96.89'

VOL. 107, PG. 133

Konwal

13.39 Ac.

N 89°43'50" W
6.81'

Lot

1291.51'

N 89°43'50" W
1298.32'
Parallel with North Line of Gov't Lot 7

Wienser

N 86°15'59" W
48.94'

NOTE: Bearings are assumed and referenced to the West
line of the SW 1/4 of Section 3, which bears N 01°58'57" E.



Scale 1" = 200'

SW Cor.
Sec. 3

Iron Pipe in Blacktop Road
W/B.C. Ref. Mon. Found



SURVEYOR'S CERTIFICATE:

I, Michael A. Tremel, a Registered Land Surveyor in the State of Wisconsin HEREBY CERTIFY that I have surveyed and mapped two parcels of land for Dorothy Konwal as delineated hereon, and that to the best of my knowledge and belief said map is a true representation of the exterior lines thereof, and that I have fully complied with the minimum standards for property surveys in the State of Wisconsin.

| | | | |
|-------------------------|--|---|--------------------|
| DATE: November 27, 2001 | TREML LAND SURVEYING, INC. 5134 AIRPORT LANE LAONA, WI 54541 PHONE 715-674-2923 | LEGEND: ○ 3/4" X 24" Rebar Set ● 2 1/2" X 48" Iron Found in Place ● 3/4" Iron pipe Found in Place ⊙ 1" Rebar Found in Place | SHT. NO. 1 OF 1 |
| DWG. NO.: 228-01 | | | |

NW Cor.
Sec. 3 2" Dia. Stamped
B.C. Mon. Found

PLAT OF SURVEY

FOR

DOROTHY KONWAL

The SW 1/4 - NW 1/4 & part of Government Lot 7, All in Section 3,
T35N R13E, Township of Lincoln, Forest County, Wisconsin

Cor. Established by
William B. Cochrane
S-1107 in 1981

N 1/16
FRAC'L NW 1/4 - NW 1/4 S 89°13'17" E
SW 1/4 - NW 1/4 1319.95'

NW Cor.
Gov't Lot 6
(NW 1/16 Sec.3)

Section 4
Section 3

Konwal

SW 1/4 - NW 1/4

39.78 Ac.

N 00°05'47" E
1318.41'

1308.68'
S 00°04'12" W

N

NW Cor.
Gov't Lot 7
(W 1/4 Sec.3)

SW 1/4 - NW 1/4
Gov't Lot 7

S 89°43'50" E
1320.47'
North Line of Gov't Lot 7

Cor. Established by
William B. Cochrane
S-1107 in 1981

Cottage

Garage

S 89°43'50" E
96.89'

VOL. 107, PG. 133

Konwal

13.39 Ac.

N 01°58'57" E
429.80'

N 01°58'57" E
2588.82'

N 89°43'50" W
6.81'

Lot

1291.51'

N 89°43'50" W 1298.32'
Parallel with North Line of Gov't Lot 7

Wienser

N 86°15'59" W
48.94'

S 17°20'09" W 449.40'
WEST SHORE DRIVE

NOTE: Bearings are assumed and referenced to the West
line of the SW 1/4 of Section 3, which bears N 01°58'57" E.



Scale 1" = 200'

SW Cor.
Sec. 3

Iron Pipe in Blacktop Road
W/B.C. Ref. Mon. Found

SURVEYOR'S CERTIFICATE:

I, Michael A. Tremel, a Registered Land Surveyor in the State of Wisconsin HEREBY CERTIFY that I have surveyed and mapped two parcels of land for Dorothy Konwal as delineated hereon, and that to the best of my knowledge and belief said map is a true representation of the exterior lines thereof, and that I have fully complied with the minimum standards for property surveys in the State of Wisconsin.

FOREST CO SURVEYOR

FILE # 351303-2001127

DATE BY



| | | | |
|-------------------------|--|---|--------------------|
| DATE: November 27, 2001 | TREML LAND SURVEYING, INC. 5134 AIRPORT LANE LAONA, WI 54541 PHONE 715-674-2923 | LEGEND: ○ 3/4" X 24" Rebar Set ● 2 1/2" X 48" Iron Found in Place ● 3/4" Iron pipe Found in Place ○ 1" Rebar Found in Place | SHT. NO. 1 OF 1 |
| DWG. NO.: 228-01 | | | |