

Sheet 1 of 4

CERTIFIED LAND CORNER RESTORATION

BEING THE NORTH SIXTEENTH CORNER BETWEEN SECTIONS 5 AND 6, TOWNSHIP 38 NORTH, RANGE 12 EAST, FOURTH PRINCIPAL MERIDIAN

COUNTY OF FOREST, STATE OF WISCONSIN





Sheet 3 of 4

CORNERS RECOVERED

1. Section Corner Common to Sections 5, 6, 31 and 32.

Recorded as document 118064, 1979.

2. North Meander Corner Between Sections 5 and 6.

The corner position is marked by a monument from the 1937 General Land Office dependent resurvey.

Corner reference recovered:
Cedar 12"

N60°E

53.67 Feet

New corner reference:
Birch 10"

N 2°W

74.72 Feet
Steel Sign Post

West

50 Foot

3. South Meander Corner Between Sections 5 and 6.

The corner position is marked by a monument from the 1937 General Land Office dependent resurvey.

Corner references recovered:		
Red Pine 18"	s 9°W	45.20 Feet
White Pine 23"	s37°W	20.85 Feet
White Pine 18"	S49°E	11.20 Feet
Steel Sign Post	NW	2.0 Feet

CORNERS ESTABLISHED

1. North Sixteenth Corner Between Sections 5 and 6.

Corner position established at proportional distance and on line between the section corner common to Sections 5, 6, 31, 32 and the quarter corner between Sections 5 and 6. The quarter corner falls in the lake.

New corner references:		
Spruce 10"	S38°E	14.13 Feet
Cedar 12"	N70°W	53.19 Feet
Steel Sign Post	Southwest	.50 Foot

Sheet 4 of 4

SURVEYOR'S AFFIDAVIT

State of Wisconsin) County of Forest) ss

I, William B. Cochrane, Land Surveyor, U.S. Forest Service and a registered land surveyor in the State of Wisconsin, hereby certify that I have surveyed the north half mile between Sections 5 and 6, Township 38 North, Range 12 East, Fourth Principal Meridian.

The plat map and the survey notes are a correct representation of the corners recovered and located.

WILLIAM B. COCHRANE S-1107 HILES, WISCONSIN SURVINION SURVINION

Land Surveyor, U.S. Forest Service

R.L.S. State of Wisconsin Certificate No. S-1107

Date of Survey: 1981

EQEIV NOV FOREST CO. CLERK Crandon, WI

H.C. Maller Company

FILE # _____BY ___

Stock No. 26273


FORES	ST CO SI	JRVEYOR
		- 1981 <i>0000</i>
DATE_		BY

Sheet 1 of 4

CERTIFIED LAND CORNER RESTORATION

BEING THE NORTH SIXTEENTH CORNER BETWEEN SECTIONS 5 AND 6, TOWNSHIP 38 NORTH, RANGE 12 EAST, FOURTH PRINCIPAL MERIDIAN

COUNTY OF FOREST, STATE OF WISCONSIN



LEGEND

- 2½ inch diameter aluminum pipe monument, 30 inches long with an aluminum cap stamped to identify the corner.
- Corners monumented and recorded.
- 1937 G.L.O. Monument.


SURVEY NOTES

The north sixteenth corner between Sections 5 and 6, T38N, R12E was established by the U.S. Department of Agriculture, Forest Service.

The north sixteenth corner was established by proportionate measurement and on line between the section corner common to Sections 5, 6, 31, 32 and the quarter corner which falls in Julia Lake.




CONVERSION FACTORS: Feet to Meters — 0.304801 Meters to feet — 3.280833



JAN 8 **1982**

Dora C. James

Scale I"= 400' 400' 0 400' scale in feet



Sheet 3 of 4

CORNERS RECOVERED

1. Section Corner Common to Sections 5, 6, 31 and 32.

Recorded as document 118064, 1979.

2. North Meander Corner Between Sections 5 and 6.

The corner position is marked by a monument from the 1937 General Land Office dependent resurvey.

Corner reference recovered:

Cedar 12" N60°E 53.67 Feet

New corner reference:

Birch 10" N 2°W 74.72 Feet Steel Sign Post West .50 Foot

3. South Meander Corner Between Sections 5 and 6.

The corner position is marked by a monument from the 1937 General Land Office dependent resurvey.

Corner references recovered:

Red Pine 18"	s 9°W	45.20 Feet
White Pine 23"	·s37°W	20.85 Feet
White Pine 18"	S49°E	11.20 Feet
Steel Sign Post	NW	2.0 Feet

CORNERS ESTABLISHED

1. North Sixteenth Corner Between Sections 5 and 6.

Corner position established at proportional distance and on line between the section corner common to Sections 5, 6, 31, 32 and the quarter corner between Sections 5 and 6. The quarter corner falls in the lake.

New corner references:

Spruce 10"	s38°E	14.13 Feet
Cedar 12"	N70°W	53.19 Feet
Steel Sign Post	Southwest	.50 Foot

HCMT Comer

Stock No. 26273

Sheet 4 of 4

SURVEYOR'S AFFIDAVIT

State of Wisconsin) County of Forest)

I, William B. Cochrane, Land Surveyor, U.S. Forest Service and a registered land surveyor in the State of Wisconsin, hereby certify that I have surveyed the north half mile between Sections 5 and 6, Township 38 North, Range 12 East, Fourth Principal Meridian.

The plat map and the survey notes are a correct representation of the corners recovered and located.

WILLIAM B.
COCHRANE
S-1107
HILES,
WISCONSIN

Land Surveyor, U.S. Forest Service

R.L.S. State of Wisconsin Certificate No. S-1107

Date of Survey: 1981