



B.M.#2 Notch on roof of 12" Birch
33' right of ϕ at sta 14+70
Elevation = 1220.4'

Ravine

Rolling Ground
Light Maple Brush
Few boulders & Rotted Stumps.

Few Hemlocks up to 10' dia.
Maple Brush. Some Bldrs.

Sta. 11+88 Galv. Iron
pipe 24.3' left of ϕ .

Sta. 12+32
Galv. Iron Pipe.

TOWN OF NASHVILLE.
Sec. 2 T.35N. R.12E.

Sta. 27+50 Ease alignment to
left to allow for curve.

Light Brush. Few rotted stumps and logs.

4" Maples: Some Surface Boulders

Sta. 11+218 Good Crusher Material
10' 1" 45' Left. 2" Hardwoods: Brush
Some Rotted Stumpage and Logs.
Few Surface Boulders

Some Stone in roadbed.

27+50
10' 0" 45' Left

Few Rotted Stumps and Logs.

Sta. 11+278 Ease alignment to
left to allow for curve.

Small Ridge.

Sec. 1 T.35N. R.12E. Fast Fall
1250' from

STA. B TO STA. 12 CUT 768 CU. YDS. FILL 579 CU. YDS. 25%
 STA. 12 TO STA. 18 CUT 655 CU. YDS. FILL 582 CU. YDS. 25%
 STA. 18 TO STA. 23 CUT 535 CU. YDS. FILL 395 CU. YDS. 25%
 STA. 23 TO STA. 29 CUT 563 CU. YDS. FILL 182 CU. YDS. 25%