State of Wisconsin

CERTIFIED	CORNER	RESTORATION

Index No.

History of original corner establishment:

Original subdivision by James L. Nowlin

Oct. 3 - Oct. 16, 1865

Hemlock Hemlock 8 9

NS6E

5 Lks. 20 Lks.

Description of corner evidence found:

1 1/4" iron pipe found wood post found



Description of monument and accessories I established to perpetuate the original location of this corner.

Reset iron pipe with a new Forest County aluminum monument

Ties:

Maple	6	N55W	47.27 feet	
Maple	6	s6ЦЕ	21.32 feet	
Maple	6	s 8w	4.27 fleet	(BT found

Dated at	Crandon	,Wis., this.		$-11\mathrm{th}^{\mathrm{da}}$	ıy of	November	
· · · · · · · · · · · · · · · · · · ·	(County Surveyor, Regi	Title	Land	Surveyo	r	Regi	
Office of Regist	ter of Deeds, County of filed in this office for	ofrecord on the	Fores	t 11.th	day of	, I hereby N ovember	certify that the within 1975
at 4 o'clo	ock						108205
By	(Register of D	edds)	I	Deputy			• `