CERTIFIED LAND CORNER RESTORATION

	ATTITUDE LAND CONTINUE RECTONATION
State of Wisconsin	
County of Forest	S.
I found evidence of the North Township 40 north	, do hereby certify that on the 15 day of May , 19 74 yest section corner of Section 5. Range 12 east , Fourth Principal Meridian, as described need I established a new monument and accessories as described hereon to per is corner:
Description of original monument	and accessories and subsequent restorations:
	concrete monument 2 feet long, 6 inches in diameter, with E, S32, S6, S5, T40N, R12E, CC 1941
Description of corner evidence for	and:
Monument found as described Hemlock 11, snag bears S57 Hemlock 19, bears S21W, 102	30E, 68.5 lks.
Description of accident accident and scribe the follow Blazed and scribe the follow Figure 8, S62E, 8.68 Set steel sign post 0.8 feet	feet.
	JEAN F. RESVICK RHINELANDER, WIS.
	SUR MIN
Sec. 5	Dated at Rhinelander Wisconsin, this 30 day of 19/19/19. 19. 74. Signature Jean F. Resvick Title Land Surveyor
	(County Surveyor, Registered Land Surveyor, or other duly authorized official)
	Surveyors Registration No. S-802 Office of Register of Deeds County of Forest
Corner monument restored	I hereby certify that the within instrument was filed in this office for record on the 8th day of August 19.74, and was filed in Boo No Restorations Page No. A-5 of County Records.
	Signature State State Title
Township 40 north , Rang	e 12 east Section 5 Index No. A-5 , Page No.