CERTIFIED LAND CORNER RESTORATION

State of Wisconsin .)	
State of Wisconsin . ss County of <u>Vilas</u>	•
I found evidence of the <u>sou</u> Township <u>41 North</u>	, do hereby certify that on the 8th day of January , 19 75, th quarter corner of Section 23, Range 12 East , Fourth Principal Meridian, as described ace I established a new monument and accessories as described hereon to personner:
Dependent Resurvey of 1941 a At proportionate distance s	et an iron post, 3 feet long, 2 inch diameter, 27 inches in marked: 1/4, S23, S26, 1941, From which:
Description of corner evidence for	ınd:
Monument as described above	. Monument was bent over by machinery
Hemlock, stump, N33 ⁰ 30'E, 58 Hemlock, S16 ⁰ W, falls in roa	Blks, scribing visible ad. No evidenœ
Description of monument and according a straightened and reset the Blazed and scribed the followaple, 13", S61°W27.60 feet Hemlock, 15", N46°W, 32.34 for Set a steel sign post north	owing new bearing trees:
Sec. 23	Dated at Three Lakes Wisconsin, this Athday of March 19.75 Signature William B. Cochrane Title Survey Technician (County Surveyor, Registered Land Surveyor, or other duly authorized official) Surveyors Registration No. S-1107 Document Number 10689
Corner monument restored	Office of Register of Deeds County of Forest I hereby certify that the within instrument was filed in this office for record on the 31st. day of March 19.75, and was filed in Book No. Restorations Page No. R-19 of County Records. Signature Register of Deeds 12 East Section 23, Index No. R-19, Page No.

4411223,0020