


Set 2"x30" iron pipe in
rotted off corner post
Made B.T.'s
16' Elm S70°E, 14.9'
13' Elm N45°E, 43.5'

Existing B.T.'s
6" Balsam N24°E, 4.9'
9" Birch S76°E, 7.0'

1/8 Corner
Set 2"x30" iron pipe.
Made B.T.'s
12" Sugar Maple S2°E, 20.3'
15" Sugar Maple S89°E, 17.6'




- = 1/2" dia. iron pipe found.
- = 2"x30" iron pipe set.
- ▨ = Existing building.

3/4" B.L.M. aluminum capped pipe
1/16" east of centerline of Hwy. 55.
Existing B.T.'s
10' Elm N39°E, 47.1'
13' Basswood S45°E, 20.5'
12' Maple S57°W, 52.7'
8' Maple N66°W, 70.0'

Parts of
SECTIONS 25, 35 & 36
T40N, R13E
Alvin Township
Forest County, Wisconsin

I, James D. Rein, Registered Land Surveyor #5-1234 hereby certify that I have surveyed the property shown hereon; that this map represents an accurate survey of a portion of said property to the best of my knowledge and belief; that I have performed this survey by order of Gamma W. Hunter and that he has agreed to release me from the requirements of Wisconsin Administrative Code S. AS 5.01.



WILDERNESS SURVEYING, INC.

James D. Rein
Registered Land Surveyor #5-1234
Dated this 9th day of June, 1976
Revised this 21st day of Sept., 1979
by order of James Brell.

FOREST CO SURVEYOR
FILE # 401325-19790921
DATE _____ BY _____

Bearings true, based
on solar observation.

Map # 135
File # 4-36-4013
Drafted by J. D. Rein